

Harvard University - McKinlock Hall
TYPE: AE08



Description:

- 1st Floor - Dining room
- Two tier 18 light traditional holders with metal accent

Details:

- Ceiling Suspended Chandelier

Work Scope:

- Existing fixture shall be disassembled and hand polished to reveal original silver finish. This includes removal of the existing lacquer, cleaning, hand polishing and application of UV Resistant clear high gloss lacquer.
- Sample reviewed and approved during site 9/20 meeting.
- Replace all missing decorative and mechanical components.
- Repair all mechanical defects.
- Replace and rewire all electrical components with UL listed products and test in accordance with UL standards. Medium base sockets to be utilized.

Notes: (chandelier 1)

- Arm #3 has two previous holes drilled on the top portion.
- Arm #9 has three previously drilled holes on the top and one on the bottom.
- Arm # 12 has one crack under the bobache.
- This damage will not be repaired as it can cause further damage to the arm and ruin the existing plating. A protective sleeve will be added on wire to protect it and drilled holes will be smoothed to prevent future damage to internal wiring.

Approval: _____ Date: _____

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

580 Grand Ave. New Haven, CT 06511

PH: 1-800-922-1469 Fax: 203-785-1184

Web: LightRestoration.com

Project: Harvard University - McKinlock Hall

Lamp: 18 3w LED B11 Medium Base Ballast: N/A


Voltage: 120v

Finish: Silver

QTY: 3

Date: 1/10/14

Type: AE08



Drilling on
Top

3

Notes: (chandelier 1 arm #3)


- Arm #3 has two previous holes drilled on the top portion.
- This damage will not be repaired as it can cause further damage to the arm and the plating. A protective sleeve will be added on wire to protect it.

Approval: _____ Date: _____

GRAND LIGHT
Historic Lighting Restoration & Custom Lighting
580 Grand Ave. New Haven, CT 06511
PH: 1-800-922-1469 Fax: 203-785-1184
Web: LightRestoration.com

Project: Harvard University - McKinlock Hall
Lamp: 18 3w LED B11 Medium Base Ballast: N/A
Voltage: 120v Finish: Silver
QTY: _____ Date: 1/10/14 Type: AE08

Harvard University - McKinlock Hall
TYPE: AE08 Damage Report; Arm #3



Drilling on
Top

3

Notes: (chandelier 1 arm #3)

- Arm #3 has two previous holes drilled on the top portion.
- This damage will not be repaired as it can cause further damage to the arm and the plating. A protective sleeve will be added on wire to protect it.

Approval: _____ Date: _____

GRAND LIGHT
Historic Lighting Restoration & Custom Lighting
580 Grand Ave. New Haven, CT 06511
PH: 1-800-922-1469 Fax: 203-785-1184
Web: LightRestoration.com

Project: Harvard University - McKinlock Hall
Lamp: 18 3w LED B11 Medium Base Ballast: N/A
Voltage: 120v Finish: Silver
QTY: _____ Date: 1/10/14 Type: AE08




Notes: (chandelier 1 arm #9)

- Arm #9 has three previously drilled holes on the top and one on the bottom.
- This damage will not be repaired as it can cause further damage to the arm and the plating. A protective sleeve will be added on wire to protect it.

Approval: _____ Date: _____

GRAND LIGHT
Historic Lighting Restoration & Custom Lighting
580 Grand Ave. New Haven, CT 06511
PH: 1-800-922-1469 Fax: 203-785-1184
Web: LightRestoration.com

Project: Harvard University - McKinlock Hall
Lamp: 18 3w LED B11 Medium Base Ballast: N/A
Voltage: 120v Finish: Silver
QTY: _____ Date: 1/10/14 Type: AE08



Notes: (chandelier 1 arm #9)

- Arm #9 has three previously drilled holes on the top and one on the bottom.
- This damage will not be repaired as it can cause further damage to the arm and the plating. A protective sleeve will be added on wire to protect it.

Approval: _____ Date: _____

GRAND LIGHT
Historic Lighting Restoration & Custom Lighting
580 Grand Ave. New Haven, CT 06511
PH: 1-800-922-1469 Fax: 203-785-1184
Web: LightRestoration.com

Project: Harvard University - McKinlock Hall
Lamp: 18 3w LED B11 Medium Base Ballast: N/A
Voltage: 120v Finish: Silver
QTY: _____ Date: 1/10/14 Type: AE08



Notes: (chandelier 1 arm #12)

- Arm # 12 has one crack under the bobache.
- This damage will not be repaired as it can cause further damage to the arm and the plating. A protective sleeve will be added on wire to protect it.

Approval: _____ Date: _____

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

580 Grand Ave. New Haven, CT 06511

PH: 1-800-922-1469 Fax: 203-785-1184

Web: LightRestoration.com

Project: Harvard University - McKinlock Hall

Lamp: 18 3w LED B11 Medium Base Ballast: N/A

Voltage: 120v

Finish: Silver

QTY:

Date: 1/10/14

Type: AE08