

Diocese of Paterson - Cathedral of St. John the Baptist
Type: DF-L



(Pre-Restoration)

Work Scope:

- Existing fixture shall be disassembled, all components shall be ultrasonically cleaned, and shall receive an application of museum grade wax.
- Repair all minor mechanical defects.
- Replace and rewire all electrical components with UL listed products and test in accordance with UL standards. Medium base sockets to be utilized.
- To be cleaned without re-finishing or re-polishing and an application of museum wax shall be applied.
- Restored fixture shall receive UL label.
- No replacement parts or components. Do not replace split rings at base of sockets.
- Provide specified lamps.
- Provide one mock-up for review.
- Replace (6) non-original chain links with replications of original chain link.
- Replace (6) mismatch bell components with similar in kind or replication of existing tulip component.
- Replace (12) non-original aluminum (brass plated) acorn finials with a brass finial. Brass finial finish to match original components.
- Add 15ft of hanging chain and clevis.
- Add safety cable.

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

104 Day St. Seymour, Ct 06483

PH: 1-800-922-1469 Fax: 203-785-1184

Web: LightRestoration.com

Project: Cathedral of St. John the Baptist

Lamp: TCP LED5E26F1127K

Socket: Medium Base

Type: Indoor/Dry

Finish: Original

Ballast: N/A

S/O #: 70912

Voltage: 120v

Glass: N/A


QTY: 12

Rev: 1

Date: 2/19/16


Type: DF-L

Diocese of Paterson - Cathedral of St. John the Baptist
Type: DF-L



Original Chain Link

(Pre-Restoration)



Non-Original Chain Link

(Pre-Restoration)

Work Scope:

- Replace (6) non-original chain links with replications of original chain link.

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

104 Day St. Seymour, Ct 06483

PH: 1-800-922-1469 Fax: 203-785-1184

Web: LightRestoration.com

Project: Cathedral of St. John the Baptist

Lamp: TCP LED5E26F1127K

Socket: Medium Base

Type: Indoor/Dry

Finish: Original

Ballast: N/A

S/O #: 70912

Voltage: 120v

Glass: N/A

QTY: 12

Rev: 1


Date: 2/19/16

Type: DF-L

Diocese of Paterson - Cathedral of St. John the Baptist
Type: DF-L



(Pre-Restoration)



(Pre-Restoration)

Work Scope:

- Replace (6) mismatch bell components with similar in kind or replication of original tulip component.

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

104 Day St. Seymour, Ct 06483

PH: 1-800-922-1469 Fax: 203-785-1184

Web: LightRestoration.com

Project: Cathedral of St. John the Baptist

Lamp: TCP LED5E26F1127K

Socket: Medium Base

Type: Indoor/Dry

Finish: Original

Ballast: N/A

S/O #: 70912

Voltage: 120v

Glass: N/A

QTY: 12

Date: 1/29/16

Type: DF-L

Diocese of Paterson - Cathedral of St. John the Baptist
Type: DF-L



Work Scope:

- Replace (12) non-original aluminum (brass plated) acorn finials with a brass finial. Brass finial finish to match original components.

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

104 Day St. Seymour, Ct 06483

PH: 1-800-922-1469 Fax: 203-785-1184

Web: LightRestoration.com

Project: Cathedral of St. John the Baptist

Lamp: TCP LED5E26F1127K Socket: Medium Base Type: Indoor/Dry
Finish: Original Ballast: N/A S/O #: 70912
Voltage: 120v Glass: N/A

QTY: 12

Date: 1/29/16

Type: DF-L