

# Yale Lanman Wright Hall

TYPE: 1



(Pre-Restoration)

## Work Scope:

- Strip to base of metal by glass bead blast.
- Pre-paint solvent clean.
- Apply 2 coats of epoxy primer.
- Apply 1 or 2 coats of satin black paint.
- Application of lacquer topcoat.
- Replace missing or damaged frosted seedy glass panels.
- Rewire using 2 lamps on circuit 1.
- Rewire using 1 lamp on circuit 2 for emergency.
- Repair minor mechanical defects and compromised fasteners.
- Replace all electrical components, rewire, and test in accordance with UL standards.

Approval: \_\_\_\_\_ Date: \_\_\_\_\_

## GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

580 Grand Ave. New Haven, CT 06511

PH: 1-800-922-1469 Fax: 203-785-1184

Web: [LightRestoration.com](http://LightRestoration.com)

## Project: Yale Lanman Wright Hall

Lamp: (3) CFL 26 Watt 4 PIN

Ballast: (2) Advance ICF2S26HILDK

Voltage: 120v

Finish: Satin Black

QTY: 3

Date: 6/11/14

Type: 1