

Type 2



(Pre-Restoration)

Work Scope:

- Existing fixture shall be disassembled and stripped of all existing finish and corrosion and application of powder coat. Color TBD
- All minor mechanical defects will be corrected.
- New Wiring and electrical components tested in accordance with UL standards. (1) Medium base socket to be utilized. 12" leads provided.
- Application of new frosted seedy panels
- Lamps by others.
- Bottom metal plate to be added to enclose bottom of fixture. Non-decorative with no finial.
- Replace 3 decorative bars are missing from the original casting on both fixtures.
- Fill all existing openings and holes with fill tiger drylac epo strong.

Approval: _____ Date: _____

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

104 Day St. Seymour, Ct 06483

PH: 1-800-922-1469 Fax: 203-785-1184

Web: LightRestoration.com

Project: First Baptist Church - Pleasanton, TX

Lamp: 60 watt

Socket: medium

Shade: glass

Finish: TBD

Ballast: N/A

S/O #: 71225

Voltage: 120

Circuits: 1

QTY: 2

Final

Date: 8/5/16

Type: 2