

Heritage Village Lighting Restoration

Type: 1



(Pre-Restoration)

Description: Chandelier

Location: Meeting House Foyer

Work Scope:

- Clean, remove existing finish, apply custom hot patina, burnish, and apply lacquer top coat.
- Repair all minor mechanical defects.
- Repair (1) broken arm and align other arms as best as possible.
- Add new heavy duty chain and period canopy replacing light duty chain and canopy.
- Replace and rewire all electrical components with UL listed products and test in accordance with UL standards. Medium base sockets to be utilized.
- Provide new mounting hardware for electrical boxes. (Owner to install code compliant electrical boxes)

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

104 Day St. Seymour, Ct 06483

PH: 1-800-922-1469 Fax: 203-785-1184

Web: LightRestoration.com

Project: Heritage Village Lighting Restoration

Lamp: 60 watt max

Socket: Medium Base

S/O #: 71499

Finish: Original

Ballast: N/A

Glass: N/A

Voltage: 120v

Circuits: 1

Type: Indoor/Dry

QTY: 1

Date: 3/29/17

Type: 1