

Sagamore Hill National Historic Site

TYPE: 58-59



(Pre-Restoration)



(Pre-Restoration)

Description:

- Double Guest Room 208

NPS Catalog Number:

- Frame: #58 SAHI 7003A T12
- Frame: #59 SAHI 7004A

Work Scope:

- Clean/Walnut blast to remove excess corrosion, apply brass rub and patina as required to blend to existing finish, application of museum grade wax
- Glass 59 cracked, crack to be repaired.
- Clean glass shield to remove any surface residue.
- No replacement glass.
- Replace and rewire all electrical components with UL listed products and test in accordance with UL standards.
- New custom wall escutcheon. (Solder existing to new code compliant escutcheon)
(see attached cutsheet)

Details:

- Electrified Wall Bracket

Approval: _____ Date: _____

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

104 Day St. Seymour, CT 06483

PH: 1-800-922-1469 Fax: 203-828-6307

Web: LightRestoration.com

Project: Sagamore Hill National Historic Site

Lamp: 1 60 watt Candelabra

Ballast: N/A

Voltage: 120v

Finish: Polished Brass

QTY: 2


Date: 11/21/13

Type: 58-59

Sagamore Hill National Historic Site

TYPE: 58-59

Escutcheon Concept



- Stamped Brass Escutcheon
- Finish to closely match existing finish

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

580 Grand Ave. New Haven, CT 06511

PH: 1-800-922-1469 Fax: 203-785-1184

Web: LightRestoration.com

Project: Sagamore Hill National Historic Site

Lamp: 1 60 watt Candelabra

Ballast: N/A

Voltage: 120v

Finish: Polished Brass

QTY: 2

Date: 03/18/13

Type: 58-59