

Sagamore Hill National Historic Site

TYPE: 89



(Pre-Restoration)



(Pre-Restoration)

Description:

- Sewing Room 310

NPS Catalog Number:

- Frame: #89 SAHI 7334A

Work Scope:

- Clean/Walnut blast to remove excess corrosion, apply brass rub and patina as required to blend to existing finish, application of museum grade wax.
- Glass 49 cracked, crack to be repaired.
- Clean glass shield to remove any surface residue.
- No replacement glass.
- Replace and rewire all electrical components with UL listed products and test in accordance with UL standards.
- Provide new escutcheon. (see attached cutsheet)

Details:

- Electrified Wall Bracket

Approval: _____ Date: _____

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

104 Day St. Seymour, CT 06483

PH: 1-800-922-1469 Fax: 203-828-6307

Web: LightRestoration.com

Project: Sagamore Hill National Historic Site

Lamp: 1 60 watt Candelabra

Ballast: N/A

Voltage: 120v


Finish: Antique Brass

QTY: 1

Date: 11/21/13

Type: 89

Escutcheon Concept



- Stamped Brass Escutcheon
- Finish to closely match existing finish

Approval: _____ Date: _____

GRAND LIGHT
Historic Lighting Restoration & Custom Lighting
104 Day St. Seymour, CT 06483
PH: 1-800-922-1469 Fax: 203-828-6307
Web: LightRestoration.com

Project: Sagamore Hill National Historic Site

Lamp:

Ballast: N/A

Voltage: 120v

Finish: Antique Brass

QTY: 1

Date: 11/21/13

Type: 89