

Trinity United Methodist Church

Type: A



(Typical Pre-Restoration Photograph)

Description: Chandelier

Location: Nave

Lights: 25

Work Scope:

- Existing fixture shall be disassembled, ultrasonically and/or hand cleaned, and walnut or soda blasted to prepare the existing raw steel surface. Application of UV resistant protective metal oil top coating.
- Replace and rewire all electrical components with UL listed products and test in accordance with UL 1598 standards. UL label on all fixtures. Medium base sockets to be utilized.
- Fabricate (36) new upper amber mica diffusers.
- Replace (36) bottom amber theatrical gel on plastic diffusers with (36) mica panels to match upper mica diffusers.
- Fabricate (1) missing lower lamp access door and finish to match.
- Add a reflector into crown of outer lampholder. Relocate socket 1 1/8" from original location for diffuse down lighting.

GRAND LIGHT

Historic Lighting Restoration & Custom Lighting

104 Day St. Seymour, Ct 06483

PH: 1-800-922-1469 Fax: 203-785-1184

Web: GrandLight.com

Project: Trinity United Methodist Church

Lamp: TBD

Socket: Medium

S/O #: 72072

Finish: Natural

Circuits: 2

Diffusers: Mica

Voltage: 120v

Ballast: N/A

Type: Indoor

QTY: 6

VOL: Final

Date: 2/13/19

Type: A